Model: 602

REPLACEMENT DROSS SKIMMER FOR 2-½ POUND SOLDER POT

American Beauty Solder pots are constructed to endure the worst that you can throw at them. A full array of replacement items are available so that you can extend the life of your solder pot by performing routine maintenance versus purchasing a whole new unit. American Beauty has designed the dross skimmer as an optional part of the solder pot. This removable dross skimmer increases operator safety through reduced risk of solder splatter and maintains solder purity and temperature better than a device that rests outside the pot on a potentially contaminated surface.

Please Note: The replacement dross skimmer is made from stainless steel. Recent studies indicate that, over time, some Pb-Free solder alloys may have the capacity to dissolve stainless steel. Therefore if you choose to utilize the dross skimmer assembly in your RoHS compliant environment, we strongly recommend the periodic evaluation of this assembly for material loss and your solder alloy for possible contamination.

ACCESSORIES

The following products can be used as Accessories for Model 602 featured on this page:

Model	Product Name
600	Mid Capacity Solder Pot



FEATURES AND BENEFITS

Removable dross skimmer increases operator safety through reduced risk of solder splatter and maintains solder purity and temperature better than a device that rests outside the pot on a potentially contaminated surface.

Dross skimmer attaches to pot via removable stem (w/ 1/4" Post)

TECHNICAL SPECIFICATIONS

Available in a 220-240 VAC?	Yes, available upon request
Product Width	3.00 in / 7.62 cm
Product Height	.50 in / 1.27 cm
Package Weight	.10 lbs / 0.05 kg
Country of Origin	US
Harmonization Code:	8515.11.0000
RoHS Compliant	Yes
WEEE Compliant	Yes
Warranty Policy	Details
User Manual	User Manual
Product Lgth	6.5

END-OF-LIFE INSTRUCTIONS

In an effort to reduce waste and comply with WEEE directive, please do not dispose of product. All American Beauty Tools are serviceable and can be repaired and/or replaced. Please contact manufacturer to make arrangements.